CR630/CR1200 Driver Installation

For Windows Vista & 7

1-1 Installation

- Power the cutter on.

- Plug your CR-630/CR-1200 into the computer.

- Close the "Found New Hardware" screen.

Found New Hardware

Windows needs to install driver software for your USB <-> Serial

Locate and install driver software (recommended)
Windows will guide you through the process of installing driver software for your device.

→ Ask me again later
Windows will ask again the next time you plug in your device or log on.

Don't show this message again for this device
Your device will not function until you install driver software.

Cancel

1-2 Installation

◆ Open the Start
Menu and select
'Control Panel'

1-3 Installation

◆ View the Control Panel in 'Classic View' by clicking 'Classic View' on the left.

◆ Open the Device Manager.

CUTTERPROS.COM

1-4 Installation

◆ Scroll down and locate the USB<-> Serial device.

1-5 Installation

◆ Right click and select 'Update Driver Software'

1-6 Installation

◆ Choose:

– "Browse my computer for driver software".

1-7 Installation

◆ Click: "Let me pick from a list of device drivers on my computer"

CutterPros.com

1-8 Installation

◆ Leave 'Show All Devices' selected and click 'Next'.

1-9 Installation

◆ Click the 'Have Disk' button.

1-10 Installation

◆ Click 'Browse'

CutterPros.com

1-11 Installation

◆ **Browse to the folder where your driver is saved.**

◆ **If installing from the disk, browse to 'Computer', select your CD/DVD drive and browse to the drivers in there.**

◆ **Select the file labeled 'ftdiport.inf' and click 'Open'.**

1-12 Installation

◆ Your folder name will now be listed in the text box.

1-13 Installation

◆ Select 'USB Serial Converter' and click 'Next'.

◆ If 'USB Serial Port' is available, select that instead.

1-14 Installation

◆ The driver will now install.

1-15 Installation

- The driver has now been successfully installed on your computer!

- When returning to the main Device Manager window, a section called:
'Ports (COM & LPT)' will list the device:
'USB Serial Port (COM#)'.

The End

Please review our tutorials for more information on particular features.
http://www.cutterpros.com/downloads for further information.
To speak with a technician, submit a ticket at
http://www.cutterpros.com/support/ or call 888-828-8776 x227

CUTTERPROS.COM